


Adafruit INA219 Current Sensor Breakout

Created by lady ada




Last updated on 2014-05-14 03:15:24 PM EDT

Guide Contents

Guide Contents	2
Overview	3
Why the High Side?	3
How does it work?	4
Assembly	5
Addressing the Boards	6
Wiring	7
Connect to the microprocessor	7
Connect to the circuit	9
Programming	11
Install the Library	
Load the Example	11
Run it!	12
Customize it	13
Library Reference	14
Construction and Initialization Functions:	14
Sensor Reading Functions:	14
Downloads	16
Software:	16
Hardware:	16

Overview

The INA219B breakout board will solve all your power-monitoring problems. Instead of struggling with two multimeters, you can use this breakout to measure both the high side voltage and DC current draw over I2C with 1% precision.



Why the High Side?

Most current-measuring devices such as our current panel meter are only good for *low side* measuring. That means that unless you want to get a battery involved, you have to stick the measurement resistor between the target ground and true ground.


Since the voltage drop across the resistor is proportional to the current draw, this means that the ground reference will change with varying current. Having a shifting ground reference can cause problems for many circuits.

The INA219B chip is much smarter - it can handle high side current measuring, up to +26VDC, even though it is powered with 3 or 5V. It will also report back that high side voltage, which is great for tracking battery life or solar panels.

How does it work?

A precision amplifier measures the voltage across the 0.1 ohm, 1% sense resistor. Since the amplifier maximum input difference is ± 320 mV this means it can measure up to ± 3.2 Amps. With the internal 12 bit ADC, the resolution at ± 3.2 A range is 0.8mA. With the internal gain set at the minimum of div8, the max current is ± 400 mA and the resolution is 0.1mA. Advanced hackers can remove the 0.1 ohm current sense resistor and replace it with their own to change the range (say a 0.01 ohm to measure up 32 Amps with a resolution of 8mA)


Assembly



The board comes with all surface-mount components pre-soldered. Additional parts are included to help integrate the INA219 breakout board into your project.



Wires can be soldered directly to the holes on the edge of the board. But for breadboard use, you will want to solder on the included 6-pin header.




The load can be connected via the header, or using the included 2-pin screw-terminal.

Addressing the Boards

If more than one INA219 breakout board is used, each board must be assigned a unique address. This is done with the address jumpers on the right edge of the board. The I2C base address for each board is 0x40. The binary address that you program with the address jumpers is added to the base I2C address.


To program the address offset, use a drop of solder to bridge the corresponding address jumper for each binary '1' in the address.



Up to 4 boards may be connected. Addressing is as follows: **Board 0**: Address = 0x40 Offset = binary 00000 (no jumpers required) **Board 1**: Address = 0x41 Offset = binary 00001 (bridge A0 as in the photo above) **Board 2**: Address = 0x44 Offset = binary 00100 (bridge A1) **Board 3**: Address = 0x45 Offset = binary 00101 (bridge A0 & A1)

Wiring


The INA219 breakout board can be powered by the 5v pin on your Arduino and communicates via I2C.




Connect to the microprocessor

- Connect GND to GND
- Connect VCC to 5v
- Then connect SDA to SDA (Analog pin 4 on pre-R3 Arduinos)
- And connect SCL to SCL (Analog pin 5 on pre-R3 Arduinos)

On R3 and later Arduinos, you can connect to the new dedicated SDA & SCL pins next to the AREF pin. On pre-R3 Megas, SDA & SCL are on pins 20 & 21.



Next we must insert the INA219 current sensor into the circuit we want to measure:





Be careful inserting noisy loads that can cause a sharp current draw, such as DC motors, since they can cause problems on the power lines and may cause the INA219 to reset, etc. When using a DC motor or a similar device, be sure to include a large capacitor to decouple the motor from the power supply, etc.

Connect to the circuit

- Connect V+ to the positive terminal of the power supply for the circuit under test.
- Connect V- to the positive terminal or lead of the load. This puts the sense resistor inline with the circuit.
- Finally, connect a wire from the negative terminal of the power supply to GND. This allows the sensor to measure the load voltage as well as the load current.

The photo below shows an INA219 breakout board configured to measure the motor supply current on an Adafruit Motor Shield.





Programming


Programming the Adafruit INA219 breakout board is simple using our library:

Install the Library

- **Download** the library from the Downloads link on the left.
- **Expand** the .zip file to the Libraries folder in your Arduino Sketchbook folder (*If you don't know where this is, open File->Preferences in the IDE and it will tell you the location of your sketchbook folder*).
- Rename the folder to Adafruit_INA219
- **Close all** instances of the IDE, then re-open one, so that the IDE will recognize the new library.

Load the Example

- Select "File->Examples->Adafruit_INA219->getcurrent"
- The "getcurrent" example code should open in a new IDE window.



Run it!

- Click on the upload button in the IDE. When it is "done uploading"
- **Open** your Serial Monitor and set the speed to 115200 baud.

The output should appear similar to the sample below:

ile Edit Sketch Tools Help					
	🎂 COM19				X
include <wire.h></wire.h>					Send
include <adafruit_ina219.h></adafruit_ina219.h>					
	Bus Voltage:	5.03 V			1
dafruit_INA219 ina219;	Shunt Voltage:				
	Load Voltage:				
oid setup (void)	Current:	28.40 mA			
uint32 t currentFrequency;					
arness_c currenterrequency;	Bus Voltage:	5.03 V			
Serial.begin(115200);	Shunt Voltage:	2.83 mV			
Serial.println("Hello!");	Load Voltage:	5.03 V			
becaute pranoant meanor);	Current:	28.10 mA			
Serial.println("Measuring volt					
ina219.begin();	Bus Voltage:				
	Shunt Voltage:				
	Load Voltage:				
oid loop (void)	Current:	28.10 mA			
	Bus Voltage:	5 02 17			
float shuntvoltage = 0;	Shunt Voltage:				
float busvoltage = 0;	Load Voltage:				
float current_mA = 0;	Current:	27.90 mA			
float loadvoltage = 0;	Guileno.	27150 100			
	Bus Voltage:	5.03 V			
shuntvoltage = ina219.getShunt	Chung Malagan				-
<pre>busvoltage = ina219.getBusVolt current mA = ina219.getCurrent</pre>	Load Voltage:				-
loadvoltage = busvoltage + (sh	Autoscroll		Newline	▼] [1152	00 baud 🔻
Serial.print("Bus Voltage: "	· Contal aviant	<pre>busvoltage); Serial.println(" V");</pre>			
		<pre>shuntvoltage); Serial.println(" "); shuntvoltage); Serial.println(" "V");</pre>			
		<pre>loadvoltage); Serial.println(" \");</pre>			
		<pre>current mA); Serial.println(" mA");</pre>			
Serial.println("");		m //			
delay(2000);					D

Customize it

You can adapt, expand or modify the example code to suit your project requirements. For a detailed description of the available library functions, see the **Library Reference** on the next page:

Library Reference Construction and Initialization Functions: Adafruit_INA219(uint8_t addr = INA219_ADDRESS);

Constructs an instance of the Adafruit_INA219. If no address is specified, the default address (0x40) is used. If more than one INA219 module is connected, it should be addressed as shown on the Assembly page and the configured address passed to the constuctor.

void begin(void);

Initializes I2C communication with the Adafruit_INA219 device using the default configuration values.

Example:



Sensor Reading Functions:

float getBusVoltage_V(void);

Reads the voltage between GND and V-. This is the total voltage seen by the circuit under test. (Supply voltage - shunt voltage).

The return value is in Volts.

float getShuntVoltage_mV(void);

Reads the voltage between V- and V+. This is the measured voltage drop across the shunt resistor.

The return value is in Milivolts.

float getCurrent_mA(void);

Reads the current, derived via Ohms Law from the measured shunt voltage.

The return value is in Milliamps.

Example:

float shuntvoltage = 0; float busvoltage = 0; float current_mA = 0; float loadvoltage = 0;
<pre>shuntvoltage = ina219.getShuntVoltage_mV(); busvoltage = ina219.getBusVoltage_V(); current_mA = ina219.getCurrent_mA(); loadvoltage = busvoltage + (shuntvoltage / 1000);</pre>
Serial.print("Bus Voltage: "); Serial.print(busvoltage); Serial.println(" V"); Serial.print("Shunt Voltage: "); Serial.print(shuntvoltage); Serial.println(" mV"); Serial.print("Load Voltage: "); Serial.print(loadvoltage); Serial.println(" V"); Serial.print("Current: "); Serial.print(current_mA); Serial.println(" mA");

Serial.println("");

Downloads

Software:

An Arduino Library - complete with example code (http://adafru.it/aRj)

Hardware:

Complete Eagle files for the INA219 breakout board (http://adafru.it/aRk) Data Sheet for the INA219 chip (http://adafru.it/aRl)